

www.nandira.com



Sbright Pickling Gel

Clean weld joints

Fast Acting


Easy to apply

Enhances Longitivity

Restores shine

Saves Cost











How to use?

- Clean Surface: Remove any loose debris from the metal.
- Apply Gel: Spread evenly with a brush or cloth.
- Wait: Allow gel to sit for 10 to 15 minutes.
- Rinse Off: Wash away gel with water and dry the surface.



Use proper safety gear and work in a well ventilated area. Avoid direct skin contact

Other Products:-









Scan to know more