MIDC Kondhane, Bandhanpada, Kudus, Taluka Wada, District - Thane Maharashtra, India. www.nandira.com, solutions@nandira.com

MSDS OF SBRIGHT- PASS

PRODUCT: SBRIGHTPASS: SS PASSIVATION

Section I

Manufacturer's Name: NANDIRA CHEMICALS

THANE

Section II.

Hazardous Ingredients/Identity Information

NA - Not Applicable NO HAZARDOUS CHEMICALS USED

Section III.

Physical/Chemical Characteristics NA . Not Applicable

Boiling Point: NA Melting Point: NA Specific Gravity: 1 Vapor Pressure: NA Vapor Density: NA

Evaporation Rate: (Water = 1): 1 Solubility in Water: 100%

Appearance and Odor: COLOURLES, ODOURLESS-CHEMICAL ODOUR

Section IV.

Fire and Explosion Hazard Data NFPA Rating:

Health 1 Flammability 0 Reactivity 1

Flash Point (Method Used) : None

Flammability Limits: NA LEL: NA UEL: NA

Extinguishing Media : NON FLAMABLE.

Special Fire Fighting Procedures : NON FLAMABLE.

Section V.

Reactivity Data

Stability

Stable Conditions to Avoid: None Incompatibility (Materials to avoid) NA.

Hazardous Decomposition or Byproducts: None

Hazardous Polymerization: Will not appear.

Section VI.

Health Hazard Data

Routes of Entry

Inhalation : X Skin : X

Ingestion : Not likely

Health Hazards: NON HAZARDOUS Signs and symptoms of exposure:

- NA

Medical conditions generally aggravated by exposure:

NA

Emergency first aid procedures:

- Eye or skin contact: Flush immediately with copious running water for at least 15 minutes. See physician
- If ingested: DO NOT induce vomiting. Give large quantities of milk or water. Get immediate medical attention.

Section VII.

Precautions for Safe Handling and Use

Steps to be taken in case material is released or spilled:

Flush with water.

Waste disposal method:

NO SPECIAL METHODES FLUSH WITH WATER

Precautions to be taken in handling and storing:

Wear protective equipment when handling.

Do NOT wear contact lenses.

In case of spill-Remove and discard contaminated clothing and launder before reuse.

Discard contaminated shoes.

Other Precautions:

Do not reuse.

Dispose of in accordance with applicable government regulations.

Section VIII.

Control Measures

Respiratory Protection (Specify Type): Not needed IF adequate ventilation is provided.

Ventilation: Local exhaust

Special: NA

Mechanical (General)? Not recommended.

Other? NA

Protective Gloves: GENERAL RUBBER GLOVES

Eye protection: Chemical goggles.

Other protective clothing or equipment: No special clothes general aperone will work.

Work/Hygienic Practices:

Do not reuse emptied containers.

Clean spill immediately.

Do not eat or keep food in work area.

Wash hands before eating.

